# Oil Field Environmental Incident Summary

**Responsible Party:** STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: HAWKEYE 16-21 #3H

Field Name: TODD Well File #: 26485

Date Incident:1/11/2015Time Incident:23:30Facility ID Number:County:WILLIAMSTwp:154Rng:101Sec:16Qtr:

**Location Description:** 

Submitted By: Jason Percle Received By:

Contact Person: Jason Percle

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 2.5 Barrels 2.5 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

7' x 5' Contaminated soil.

Areal Extent:

# Potential Environmental Impacts:

Contaminated soil.

# Action Taken or Planned:

Truck pusher will more diligently watch the levels in the tanks to prevent this issue in the future. MBI has been asked to have two experienced pushers on location several times.

Wastes Disposal Location:

Agencies Involved:

# **Updates**

Date: 1/16/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.